



# DOCUMENT CHANGE REQUEST

DCR number            395            Changes required for: General  
Date: 2008/02/28            Date sent: 2008/02/28  
Status: IMPLEMENTED

Originator: Samuel SAVIN  
Organisation: CNES

Title:            Diodes, Silicon, Power Rectifier , High Efficiency, Fast Recovery, based on type BYW81-200

Number:            5103/029            Issue:            3

Other documents affected:

Page:

Paragraph 1.8, page 9

Paragraph:

Paragraph 1.8, page 9

Original wording:

Proposed wording:

See attached document

Justification:

Error during implementation of DCR 272:  
Functional diagram has not been updated for variant 05, when new drawing added to harmonize this SMD.5 package outline with all other ESCC specification with this STM package

Attachments:

Document\_BYW81-200.pdf, null

Modifications:

N/A

Approval signature:

Date signed:


2008-02-28

## 1.8 FUNCTION DIAGRAM

### Variant 05

Terminal 1 and 2: Anode

Terminal 3: Cathode



### **JUSTIFICATION**

Error during implementation of DCR 272:

Functional diagram has not been updated for variant 05, when new drawing added to harmonize this SMD.5 package outline with all other ESCC specification with this STM package.