DOCUMENT CHANGE REQUEST

DCR number	**1664**	Changes required for: General	Originator: Pierre Gourdon
Date: 2024/09/10		Date sent: 2024/04/19	Organisation: Exens Solutions
Status: IMPLEMENTED			

Title:	Diodes Microwave Silicon PIN Ultra-Fast Switching, based on types DH50101 to DH50107		
Number:	5513/038	Issue:	8

Other documents affected:

Page:

9

Paragraph:

1.5

Original wording:

In the table, the DC reverse voltage is set at -70V

Proposed wording:

In the table, the DC reverse voltage should be set at -100V

Justification:

This is a typo which is coming from update of the specification from issue 4 to issue 5 and nobody detected it.

Attachments:

N/A

Modifications:

N/A

Approval signature:

Date signed:

2024-09-10