



DOCUMENT CHANGE REQUEST

DCR number 923 Changes required for: General

Date: 2015/05/08

Date sent: 2015/03/24

Originator: Steve Thacker

Organisation: ESCC Executive Secretariat

Status: IMPLEMENTED

Title: Accessories for Rectangular Connectors 3401/001 and 3401/002 and Connector Savers 3401/020

Number: 3401/022 Issue: 9

Other documents affected:

Page:

9 & 10

Paragraph:

Figure 2(a)

Original wording:

See 3401/022 issue 9 Figure 2(a)


Proposed wording:

Renumber the notes in the last column of the 2 dimension tables in Figure 2(a) (on pages 9 & 10) for Screw Lock Assembly (Female), such that:

- 1 is changed to 3
- 2 is changed to 4
- 3 is changed to 5
- 4 is changed to 6
- 5 is changed to 7
- 6 is changed to 8

Justification:

Correction of editorial error

Attachments:
N/A
Modifications:
N/A
Approval signature:

Date signed:
2015-05-08