



DOCUMENT CHANGE REQUEST

DCR number 1363 Changes required for: General

Date: 2020/10/20

Date sent: 2020/07/23

Originator: P. Landeau

Organisation: TE Connectivity
Deutsch

Status: IMPLEMENTED

Title: Contacts Electrical Crimp for 3401/007 and 3401/008 Connectors

Number: 3401/009

Issue: 7

Other documents affected:

Page:

10
&
13

Paragraph:

§ 3 FIGURE 2 - PHYSICAL DIMENSIONS variant 05 (dimensions table page 10)
&
§ 3 FIGURE 2 - PHYSICAL DIMENSIONS variant 06 (dimensions table page 13)

Original wording:


Diameter L (Inspection hole) for variants 05 and 06 is :
Min. 0.67
Max. 0.81

Proposed wording:

Diameter L (Inspection hole) for variants 05 and 06 is :
Min. 0.45
Max. 0.61

Justification:

The inspection hole maximum diameter must be less or equal to the minimum internal diameter of the contact bucket, here diameter G (for variants 05 and 06) min: 0.61, otherwise there will be traces in the bucket, detrimental to the wire insertion. Our drawings have always been quoted that way, and parts delivered since at least 22 years in the proposed configuration.

| |
|--|
| Attachments: |
| N/A |
| Modifications: |
| N/A |
| Approval signature: |
|  |
| Date signed: |
| 2020-10-20 |