



DOCUMENT CHANGE REQUEST

DCR number 799 Changes required for: General

Date: 2014/02/27

Date sent: 2013/05/16

Status: IMPLEMENTED

Originator: Steve Thacker

Organisation: ESCC Executive
Secretariat

Title: Internal Visual Inspection of Electromagnetic Relays

Number: 2043600

Issue: 1

Other documents affected:

2045000-1, 2045010-1, 2049010-1, 2054009-1, 2055000-1, 2093000-1, 21300-3, 2139020-2, 2263000-2, 2263010-2, 2263202-2, 2263400-1, 2263501-1, 2263502-1, 2263600-2, 2264000-1, 2265000-1, 2265010-1, 2269000-1, 2269010-1, 22800-1, 24300-2, 2439000-1, 24400-1, 25000-1, 25200-1, 3001/030-4, 3002-1, 3006-1, 3006/007-1, 3006/019-1, 3006/020-1, 3009/003-4, 3010-1, 3010/004-1, 3010/005-1, 3010/006-1, 3010/008-1, 3010/010-1, 3010/011-1, 3010/012-1, 3010/013-1, 3010/014-1, 3010/015-1, 3010/016-1, 3010/017-1, 3202/019-1, 3202/020-1, 3202/025-1, 3401/009-3, 3401/012-3, 3601/002-1, 9020-2

Page:

Specs fully retyped using alternate publishing software (was GlobalView or Framemaker; is now WORD2010)

Paragraph:

All

Original wording:


See each original spec (editorial changes only)

Proposed wording:

Only editorial changes to implement the alternate publishing software (WORD2010)

Justification:

replacement of obsolete software

Attachments:
N/A
Modifications:
N/A
Approval signature:

Date signed:
2014-02-27