



DOCUMENT CHANGE REQUEST

DCR number		1619		Changes required for: General		Originator: Steve Thacker	
Date: 2024/09/10				Date sent: 2023/12/11		Organisation: ESCC Executive Secretariat	
Status: IMPLEMENTED							
Title:	Relays Electromagnetic Latching 28Vdc 10A 2PDT						
Number:	3602/001		Issue:	5			
Other documents affected:							
3602/009-8							
Page:							
See below & attached spec mark-ups							
Paragraph:							
See below & attached spec mark-ups							
Original wording:							
as per current issue (3602/001 issue 5 & 3602/009 issue 7)							
Proposed wording:							
<p>Correct the various figures in regard of the terminal Y1 & Y2 lengths (i.e delete dimension E1) and, where applicable, add the missing header terminal spacing details (dimensions D & D1) as follows.</p> <p>See attached spec mark-ups for details:</p> <p>1) 3602/001 Page 10, Variant 05</p> <p>2) 3602/009 Pages 8 to 13, all Variants</p> <p>Variants 03/13 & 05/15: correct Y1, Y2 lengths.</p> <p>All Variants: add missing dimensions D & D1 (by change to figure 1.6.3 & addition of note 2 to all other figures)</p>							
Justification:							
Correction of errors introduced by earlier DCRs (709 & 1139)							

Attachments:

escc3602001iss_draft_6a_in_review.docx, escc3602009iss_draft_8a_in_review.docx

Modifications:

N/A

Approval signature:



Date signed:

2024-09-10