



DOCUMENT CHANGE REQUEST

DCR number 371

Changes required for: N/A

Originator: andre UGUEN

Date: 2007/07/25

Date sent: 2007/07/25

Organisation:

Status: IMPLEMENTED

Title: CMOS 8-Stage Shift and Store Bus Register with Synchronous Serial Outputs and 3-State Parallel

Number: 9306/026

Issue: 2

Other documents affected:

Page:

1.10 TRUTH TABLE AND TIMING DIAGRAM
page 14

Paragraph:

1.10 TRUTH TABLE AND TIMING DIAGRAM
page 14

Original wording:

Proposed wording:

timing diagram is wrong.

Justification:

during migration from old ESA/SCC form to ESCC form, the diagram was copied and an error was introduced: the second negative pulse of STR shall start at the next falling front of CLK (in the same time as OE).

Good diagram is proposed in attached file

Attachments:

diagram_HCC4094.pdf, null

Modifications:

N/A


Approval signature:

A handwritten signature in black ink, appearing to read "R. S. Hart" with a long horizontal stroke extending to the right.

Date signed:

2007-07-25

SCHEMATIC DIAGRAMS



TIMING DIAGRAM

