

DCR : Deleted variants

Due to no order since 6 years, Exens solutions decided to stop the qualification of some variants

8 details Specifications should be updated :

5513/031-5513/032-5513/033-5513/034-5513/036-5513/037-5513/038--
5512/023

More details below

DCR Deleted variants

ESCC Spec No.	Qualified Var	Delete Var	Component type
5513/031	01 to 56 01 to 49 and 57 to 63	50 to 56	DH 50151 to DH 50157
5513/032	01 to 40 01 to 35 and 41 to 45	36 to 40	DH 50033 to DH 50037
5513/033	01 to 70 01 to 63 and 71 to 79	64 to 70	DH 50201 to DH 50209
5513/034	01 to 41 01 to 36 and 42 to 47	37 to 41	DH 50251 to DH 50256
5513/036	01 to 48 01 to 42 and 49 to 54	43 to 48	DH 50052 to DH 50057
5513/037	01 to 56 01 to 49 and 57 to 63	50 to 56	DH 50071 to DH 50077
5513/038	01 to 56 01 to 49 and 57 to 63	50 to 56	DH 50101 to DH 50107

DCR Deleted variants

ESCC Spec No.	Qualified Var	Delete Var	Component type
5512/023	01 to 09 01 to 07 and 73	08 to 09	DH 76010
5512/023	10 to 18 10 to 16 and 74	17 to 18	DH 76015
5512/023	19 to 27 19 to 25 and 75	26 to 27	DH 76022
5512/023	28 to 36 28 to 34 and 76	35 to 36	DH 76033
5512/023	37 to 45 37 to 43 and 77	44 to 45	DH 76047
5512/023	46 to 54 46 to 52 and 78	53 to 54	DH 76068
5512/023	55 to 63 55 to 61 and 79	62 to 63	DH 76100
5512/023	64 to 72 64 to 70 and 80	71 to 72	DH 76150