

DOCUMENT CHANGE REQUEST

1161 DCR number Changes required for: General Originator: Steve Thacker Date: 2018/07/13 Organisation: ESCC Executive Date sent: 2018/05/29 Secretariat Status: IMPLEMENTED Title: Power Inductors, Moulded, SMD, based on Series SESI Number: 13 3201/009 Issue: Other documents affected: Page: 8 Paragraph: Para. 1.4.2: RANGE OF COMPONENTS - VARIANT 04 (SESI 18WR) Original wording: See 3201/009 Page 8 Proposed wording: Delete last 2 rows of table for Variant 04; SESI 18WR. i.e.: L = 1000uHL = 2300uHJustification: Typographic error introduced in an earlier revision (during implementation of DCR860). These 2 items are not supported by Manufacturer Exxelia-Microspire Attachments: N/A Modifications: N/A Approval signature: Survoy Resu Date signed: 2018-07-13