

DOCUMENT CHANGE REQUEST

1296 Originator: LEROY DCR number Changes required for: MRB decision Date: 2019/11/14 Organisation: SMITHS Date sent: 2019/09/25 INTERCONNECT -Status: IMPLEMENTED Title: Contacts Electrical Crimp Wire-Wrap Solder and Saver for 3401/016 Connectors Number: 3401/017 Issue: 4 Other documents affected: Page: 22 Paragraph: Original wording: Proposed wording: Justification:

Add in ESCC 3401-017 - table 6 page 22 - n°19 Maintenance aging - 5 contacts assembly / disassembly instead of 9

Temporary change of the retention test specification (see NCCS_2CSMI901)

requested in ESCC 3401 (article 9-27)



DOCUMENT CHANGE REQUEST

1296 DCR number Changes required for: MRB decision Originator: LEROY Date: 2019/11/14 Date sent: 2019/09/25 Organisation: SMITHS **INTERCONNECT -**Status: IMPLEMENTED Title: Contacts Electrical Crimp Wire-Wrap Solder and Saver for 3401/016 Connectors Number: 4 3401/017 Issue: Other documents affected: Page: Paragraph: Original wording: Proposed wording: Justification: Attachments: N/A Modifications: Table 6 No. 19 shall not be changed as proposed in the Justification section of the DCR. A new Appendix 'A', "Agreed Deviations for Smiths Interconnect (F)", shall be added to new Page 23 of the spec instead. Details are as follows: Items affected: "Para. 4.2.4 Deviations from Qualification Tests (Chart IV)" and "Para. 4.2.5 Deviations from Lot Acceptance Tests (Chart V)" Description of Deviations (applicable to both Items): "Para. 9.27, Maintenance Aging, (a) Procedure, number of cycles: The number of cycles may be reduced from 9 to 5."

Approval signature:
duoran Peru
Date signed:
2019-11-14