



DOCUMENT CHANGE REQUEST

DCR number	778	Changes required for:	General	Originator:	Steve Jeffery
Date:	2013/06/13	Date sent:	2013/02/20	Organisation:	ESCC Executive
Status:	IMPLEMENTED				

Title: Contacts Power Crimp-Type and Solder Type for 3401/001 and 3401/002 Connectors

Number: 3401/040 Issue: 4

Other documents affected:

Page:

9

Paragraph:

Figure 2(b), dimensions table.

Original wording:

"C max."; "dia. E max."; "dia. F max."; "dia. G max."

Proposed wording:

"C min."; "E ref."; "dia. F min."; "dia. G ref."

Justification:

Typo. errors have inadvertently been introduced during the implementation of 3401/040 Issue 4; revert to the previous (correct) column headings. These are editorial changes only.

Attachments:

N/A

Modifications:

N/A

Approval signature:

Date signed:

2013-06-13