



## DOCUMENT CHANGE REQUEST

DCR number 959 Changes required for: General

Originator: Celine Davenel

Date: 2016/02/05

Date sent: 2015/11/13

Organisation: Radiall

Status: IMPLEMENTED

Title: RF Coaxial Connectors, Type SMA 2.9, 50 Ohms (Male Contact)

Number: 3402/021

Issue: 4

Other documents affected:

3402/022-4, 3402/023-5, 3403/008-5, 3403/009-4

Page:

page 9 and 10 in each specification

Paragraph:

female and male interface

Original wording:

female interface dimension 10 =2.4-2.6 and 11=2.4-2.68  
male interface dimension 7=1.22-1.4 , 9= 0.493-0.784 and 11=1.3-1.4  
see extract of specification enclosed for change

Proposed wording:

female interface dimension 10 =2.8-3.2 and 11=2.8-3.28  
male interface dimension 7=1.42-1.6 , 9= 0.693-0.984 and 11=1.5-1.6  
see extract of specification for change

Justification:

to correct mistake from DCR 770 and also to include SMA29 interface of loads and attenuators- see justification letter enclosed

Attachments:

2015\_justification\_for\_new\_dcr\_about\_sma2.9.pdf, 3402022\_issue\_3\_page\_9.jpg, 3402023\_issue\_4\_page\_9.jpg, 3403009\_issue\_4\_page9.jpg, 3402023\_issue\_4\_page\_10.jpg, 3402021\_issue\_3\_page\_10.jpg, 3402022\_issue\_3\_page10.jpg, 3403009\_issue\_4\_page10.jpg, 3403008\_issue\_4\_page10.jpg, 3402021\_issue\_3\_page\_9.jpg, 3403008\_issue\_4\_page\_9.jpg

Modifications:

N/A

Approval signature:



Date signed:

2016-02-05