



## DOCUMENT CHANGE REQUEST

DCR number 1303 Changes required for: General

Date: 2019/12/13

Date sent: 2019/10/11

Status: IMPLEMENTED

Originator: Steve Thacker

Organisation: ESCC Executive  
Secretariat

Title: Accessories for Connectors Microminiature 3401/029, 3401/077 and Connector Savers 3401/041

Number: 3401/032

Issue: 11

Other documents affected:

Page:

-

Paragraph:

-

Original wording:

-

Proposed wording:

-

Justification:

Additional changes to this DCR as requested by Manufacturer Glenair related to specific components and options supported by Glenair. All changes as shown in the new DCR attachment "ESCC3401032Iss12D in review per DCR" were reviewed and agreed with C&K Axon.



## DOCUMENT CHANGE REQUEST

DCR number 1303 Changes required for: General

Date: 2019/12/13

Date sent: 2019/10/11

Status: IMPLEMENTED

Originator: Steve Thacker

Organisation: ESCC Executive  
Secretariat

Title: Accessories for Connectors Microminiature 3401/029, 3401/077 and Connector Savers 3401/041

Number: 3401/032

Issue: 11

Other documents affected:

Page:

Various, see below

Paragraph:

Various, see below

Original wording:

As per 3401/032 issue 11

Proposed wording:

The following additions are proposed by Manufacturer Glenair; see attachment 3401/032 Draft 12C for full details.  
Note: the attachment also details the changes proposed per related DCR1287.

Table 1(a) & Figure 2: add new Variants 59 to 68 ( Screwlock for Connectors GMR7580, GMR7590)

Justification:

This DCR is raised on behalf of Glenair.  
Changes are required to add new variants.

Note: This DCR should be considered together with DCR1287.

Attachments:

escc3401032iss12c\_in\_review\_per\_dcr.docx

Modifications:

Additional changes as follows shall apply as requested by Manufacturer Glenair and as discussed and agreed with other supporting Manufacturers, C&K, Axon, in order to be consistent across all 3 Manufacturers:

see attached "ESCC3401032Iss12D in review per DCR" for full change details (changes highlighted by text colour).

In New Figure 2 for Variants 64 to 68, the torque values for the male & female sides given in each figure, are corrected.

Approval signature:

A handwritten signature in black ink, appearing to read "Andrew R. [unclear]".

Date signed:

2019-12-13