



DOCUMENT CHANGE REQUEST

DCR number	249	Changes required for:	N/A	Originator:	Kimmo Immonen
Date:	2006/04/04	Date sent:	2006/04/04	Organisation:	
Status:	IMPLEMENTED				

Title:	Connectors Electrical Rectangular Non-Removable Solder Bucket PCB and Wire-Wrap Contacts				
--------	--	--	--	--	--

Number:	3401/001	Issue:	2
---------	----------	--------	---

Other documents affected:

3401/002-3

Page:

Page 16, Figure 2(b), VARIANT 02-...

Paragraph:

Page 16, Figure 2(b), VARIANT 02-...

Original wording:

Proposed wording:

In figure 2(b) is presented the contact layout of D-connector 78 Contact, Gauge 22. The contact layout/numbering is incorrect. In picture there are presented incorrectly 79 contacts.

Justification:

Correct contact layout presented in attachment.

Attachments:

DSubContacts.pdf, null

Modifications:

N/A


Approval signature:

Date signed:

2006-04-04


Plug Contact Cavity Arrangements — High Density

Face View Pin Insert




Shell Size
Contact Arrangement
Contact Size

E
15
#22




Shell Size
Contact Arrangement
Contact Size

A
26
#22




Shell Size
Contact Arrangement
Contact Size

B
44
#22



Shell Size
Contact Arrangement
Contact Size

C
62
#22




Shell Size
Contact Arrangement
Contact Size

D
78
#22


Receptacle Contact Cavity Arrangements — High Density

Face View Socket Insert




Shell Size
Contact Arrangement
Contact Size

E
15
#22




Shell Size
Contact Arrangement
Contact Size

A
26
#22




Shell Size
Contact Arrangement
Contact Size

B
44
#22



Shell Size
Contact Arrangement
Contact Size

C
62
#22



Shell Size
Contact Arrangement
Contact Size

D
78
#22