


DOCUMENT CHANGE REQUEST


250 DCR number Changes required for: N/A Originator: Kimmo Immonen Date: 2006/04/04 Date sent: 2006/04/04 Organisation: Status: IMPLEMENTED Connector Savers Electrical Rectangular Miniature Removable Contacts, based on type D*BMA Title: Number: 3 3401/020 Issue: Other documents affected: Page: Page 9, Figure 2(b), VARIANT 02-... Paragraph: Page 9, Figure 2(b), VARIANT 02-... Original wording: Proposed wording: In figure 2(b) is presented the contact layout of D-connector 78 Contact, Gauge 22. The contact layout/numbering is incorrect. In picture there are presented incorrectly 79 contacts. Justification: Correct contact layout presented in attachment. Attachments: DSubContacts.pdf, null Modifications: N/A Approval signature: 12 (c f(an-1 Date signed: 2006-04-04

Plug Contact Cavity Arrangements — High Density

Face View Pin Insert














Shell Size Contact Arrangement Contact Size


D 78

Receptacle Contact Cavity Arrangements -High Density


Face View Socket Insert


Shell Size Contact Arrangement

Contact Size











9000000000

00000000

A 26 #22