



## DOCUMENT CHANGE REQUEST

DCR number 769 Changes required for: General

Originator: Celine Davenel

Date: 2013/07/02

Date sent: 2012/10/25

Organisation: Radiall

Status: IMPLEMENTED

Title: RF Coaxial Connectors, Type SMA 2.9, 50 Ohms (Male Contact)

Number: 3402/021

Issue: 2

Other documents affected:

Page:

page 25 on 3402/021

Paragraph:

variant 07 on 3402/021

Original wording:

variant 07 on 3402/021

D 1.52 1.54

ØE 2.57 2.7 4 Holes

ØG 4.65 4.85

H 0.09 0.1

Proposed wording:

variant 07 on 3402/021

D 1.4 1.7

ØE 2.55 2.7 4 Holes

ØG 4.46 4.66

H 0.055 0.135

see document enclosed for description of the modification.

Justification:

variant 07 on 3402/021:

First order on this variant, this typing error was detected at order review. Radiall requests this dimension modification to be in accordance with the equivalent female flange variant 04 on 3402/022.



# DOCUMENT CHANGE REQUEST

DCR number 769 Changes required for: General

Originator: Celine Davenel

Date: 2013/07/02

Date sent: 2012/10/25

Organisation: Radiall

Status: IMPLEMENTED

Title: RF Coaxial Connectors, Type SMA 2.9, 50 Ohms (Female Contact)

Number: 3402/022

Issue: 2

Other documents affected:

Page:

page 22 on 3402/022

Paragraph:

variant 03 on 3402/022

Original wording:

variant 03 on 3402/022  
D 6.19 6.26

Proposed wording:

Variant 02 on 3402/022  
D 0.65 0.95

Justification:

typing error deted by Radiall and already submitted to customer and approved at first order.

Attachments:

3402022\_iss\_2\_var03\_amended\_by\_radiall\_2010.11.05.pdf, 3402022\_iss\_2\_variant\_04.pdf, 3402021\_iss\_2\_var\_07\_amended\_by\_radiall\_2012.10.23.pdf, null

Modifications:

N/A

Approval signature:

Date signed:

2013-07-02