



DOCUMENT CHANGE REQUEST

DCR number	883	Changes required for:	General	Originator:	Steve Thacker
Date:	2014/11/17	Date sent:	2014/10/13	Organisation:	ESCC Executive Secretariat
Status:	IMPLEMENTED				

Title: Accessories for Rectangular Connectors 3401/001 and 3401/002 and Connector Savers 3401/020

Number: 3401/022 Issue: 8

Other documents affected:

Page:

9 & 10

Paragraph:

Figure 2(a):
Screw Lock Assembly (Female) (4-40)
Screw Lock Assembly (Female) (Hybrid 4-40/M3)

Original wording:

see original spec.

Proposed wording:

Amend the 2 figures for Screw Lock Assembly (Female) in Figure 2(a) as follows:

For: Screw Lock Assembly (Female) (4-40):
Amend the thread definition of the head hole to be: 4.40 UNC-2B
Add thread definition of the shaft: 4.40 UNC-2A

for: Screw Lock Assembly (Female) (Hybrid 4-40/M3):
Amend the thread definition of the head hole to be: 4.40 UNC-2B

See attached amended draft spec ("3401/022 issue 9 in progress") for details.

Justification:

Typographical errors introduced during a previous specification revision.


Attachments:

3401022_issue_9_in_progress.docx

Modifications:

N/A

Approval signature:

A handwritten signature in black ink, appearing to read "R. S. Hart" with a long horizontal stroke extending to the right.

Date signed:

2014-11-17